

**U. S. Department of Agriculture**  
**FOREST SERVICE**

E13

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 148 N. R. 29 W. 5th. P. Mer.  
Section Corner common to Sections

3, 4, 9, and 10

Corner consists of a in Center of Roadcut in place  
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Count	B.Ts.		
	Orig. Bt.		
B.T.	B.t.		

Species Spruce Spruce

Diameter 9" 9"

Bearing S. 34° E. S. 39° E.

Distance 59 102

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

H. Hoard

(Signature)

11/16/39

(Date)

Compass Man

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of *Post 18 Sec. Corner*

*6* inches diameter, on the South

Metal Location Poster is on a Sec. Line Post



(Make sketch of topography near Corner)