

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

R-15

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 29 W. 5 Mer.

1/4 Cor. Corner common to Sections
 22, 27, and

Corner consists of a Wood Post (not) in place
 State condition Fair

Dimensions above ground 2' x 2" - 3' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4 22		1/4 27	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 22		1/4 27	
12 Lks.		8 Lks.	

Species Jack P. Jack P.
 Diameter 10" 10"
 Bearing N- 55° W
 Distance 12 Lks. 8 Lks.

Do you believe this to be a genuine Land Office Corner? Yes
 If not, why?

(Signature)

(Date)

(Title)

POSTER ON Road

Corner again.

Give any further facts which will aid in finding this


3 chains distant.

from which this Corner bears N-

side of 1 1/4 CORN

tree 8 1/2 inches diameter, on the South

Metal Location Poster is on a



(Make sketch of topography near Corner)