

U. S. Department of Agriculture
FOREST SERVICE

*P17 Posted
12/12/40*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 29W 5th Mer.

Quarter Corner common to Sections
22, and 23

Corner consists of a Wood post (not) in place
State condition good

Dimensions above ground 4" 4" 20" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

$\frac{1}{4}$			$\frac{1}{4}$
S22			S23
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$	$\frac{1}{4}$		
S22	S23		
BT	BT		

Species Spruce Spruce

Diameter 10 6

Bearing N88° 30' E S58W

Distance .30 .42

Do you believe this to be a genuine Land Office Corner? No
If not, why? County corner


Walter K. ...
(Signature)

10/14/40
(Date)

Prof. ...
(Title)

COPIES OF THE REPORTS OF THE
COMMISSIONERS OF THE GENERAL LAND OFFICE
FOR THE YEAR 1919

Corner again.
Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the 1n. sec. 22
Metal Location Poster is on a
The berrring tree



(Make sketch of topography near Corner)