

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

P18

chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 29W 5th Mer.

1/16#9

Corner common to Sections

23, and

Corner consists of a Wood post (not) in place

State condition good

Dimensions above ground 4" 4" 20" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<u>1/16</u> <u>#9</u> <u>23</u>		
--	---------------------------------------	--	--

<u>BT</u>	<u>BT</u>	<u>BT</u>	
-----------	-----------	-----------	--

Species J. Pine Aspen Elm

Diameter 12 14 10

Bearing N63E S12E S72W

Distance 56 46 44

Do you believe this to be a genuine Land Office Corner? No

If not, why? County corner

Walter Haberk

(Signature)

10/14/40


(Date)

Proj. Asst.

(Title)

Faint, illegible text at the top of the page, possibly bleed-through from the reverse side.

Corner again.  
Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the berring tree  
Metal Location Poster is on a the J. Pine



(Make sketch of topography near Corner)