

**U. S. Department of Agriculture**  
**FOREST SERVICE**

**Chippewa** NATIONAL FOREST

R19

**CORNERS OF THE PUBLIC SURVEY**

T. 148N R. 29W 5th Mer.  
quarter Corner common to Sections

23, and 26

Corner consists of a wood post (not) in place

State condition good

Dimensions above ground 3" 3" 16" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

BT

BT

Species J. Pine J. Pine

Diameter 6" 6"

Bearing S49E N34E

Distance .45 .95

Do you believe this to be a genuine Land Office Corner? **No**

If not, why? County corner

Walter H. Hulse


(Signature)

10/14/40  
(Date)

Proj. post  
(Title)

Faint, illegible text on ruled lines, possibly bleed-through from the reverse side of the page.

Corner again.  
Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the n. sec. 23  
Metal Location Poster is on a The berrying tree



(Make sketch of topography near Corner)

**U. S. Department of Agriculture**  
**FOREST SERVICE**

Posted  
12/15/40

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 148N R. 29W 5th Mer.

1/16#9

Corner common to Sections

23, and

Corner consists of a Wood post (not) in place

State condition good

Dimensions above ground 4" 4" 20" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<u>1/16#9</u> <u>S23</u>		
BT	BT	BT	

Species J. Pine Aspen Elm

Diameter 12 14 10

Bearing 56 46 44

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? County corner


Walter H. Hulse  
(Signature)

10/14/40  
(Date)

Asst. Insp.  
(Title)

Faint, illegible text on the top half of the page, possibly bleed-through from the reverse side.

Corner again.  
Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a  
The J. Pine



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N. R. 29W. 5th P. Mer.

Section Corner common to Sections

21, 22, 27, and 28

Corner consists of a Tamc. Post (~~not~~) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

0719 BTs.

--	--	--	--

<u>BT.</u>	<u>BT.</u>	<u>BT</u>	
------------	------------	-----------	--

Species Tamc. Sp. Tamc. Sp. Tamc. Sp.

Diameter 8" 4" 8"

Bearing N. 77° W. N. 5° E. S 30° E.

Distance 8 33 1/2 39

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_



John A. Goltzong

(Signature)


Jr Civil Eng.

(Title)

11/29/38

(Date)

Metal Location Poster is on a *B. Spruce* tree *4* inches diameter, on the *SE* side of *Tree* from which this Corner bears *0.17* chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 148N. R. 29W. 5th P. Mer.