

U. S. Department of Agriculture

FOREST SERVICE

*posted C71*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 29 W. 5 Mer.

4 Corner common to Sections 1, and 2

Corner consists of a Post (not) ~~in place~~


State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_ *Aspen Stamp*

Diameter \_\_\_\_\_ *14"*

Bearing \_\_\_\_\_ *N 72° W* \_\_\_\_\_ *N 34° E*

Distance \_\_\_\_\_ *15 Links* \_\_\_\_\_ *16 Links*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*Walter Johnson*

(Signature)

*Estimator*

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

22 ft chains distant.

from which this Corner bears


N 80° W.

side of

tree 6 inches diameter, on the

Metal Location Poster is on a

Birch



(Make sketch of topography near Corner)

T. 148 N. R. 29 W. 5 Mer.