

U. S. Department of Agriculture

FOREST SERVICE

posted E73

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148* R. *29* S. Mer.

Section Corner common to Sections *1*, *6*, *7*, and *12*

Corner consists of a *Post* (not) in place



State condition *Good*

Dimensions above ground *4'* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>Sec 1</i>	<i>Sec 6</i>	<i>Sec 7</i>	<i>Sec 12</i>
<i>BT</i>	<i>BT</i>	<i>BT</i>	<i>BT</i>

Species <i>Stump</i>	<i>Sedus</i>	<i>Balden</i>	<i>Tamarac</i>
Diameter _____	<i>14 in</i>	<i>10</i>	<i>12</i>
Bearing <i>SW</i>	<i>NE</i>	<i>SE</i>	<i>SW</i>
Distance <i>1/2 ch</i>	<i>2 ch</i>	<i>2 ch</i>	<i>1 ch</i>

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

(Signature)

(Date)

(Title)

Corner again.


Give any further facts which will aid in finding this

from which this Corner bears *about 20 links* chains distant.

side of *East*

tree *6* inches diameter, on the *South*

Metal Location Poster is on a *White Post*



(Make sketch of topography near Corner)