

U. S. Department of Agriculture  
FOREST SERVICE

*Forest A 25*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *19A* R. *2829* *5* Mer.

*Sec.* Corner common to Sections

*1, 6,* and

Corner consists of a *None* (not) in place

State condition

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_ *Spruce* \_\_\_\_\_

Diameter \_\_\_\_\_ *9"* \_\_\_\_\_

Bearing \_\_\_\_\_ *S. 45° E.* \_\_\_\_\_

Distance \_\_\_\_\_ *16 Lk.* \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*R. G. McEachin*  
(Signature)

*2-23-35*  
(Date)

*Estimator*  
(Title)

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

Corner again.  
 COR. RESET - 2 1/2 - 14" Spruce  
 Hub

Give any further facts which will aid in finding this

20 ft. ~~shades distant.~~

from which this Corner bears

N 88° E

side of


Sec. 6011

tree 8 inches diameter, on the

EAST

Metal Location Poster is on a

Spruce



(Make sketch of topography near Corner)

T. 148 R. 29 Mer. 5

Form 874-9 - Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

A-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 29 S. Mer.  
Sec. Corner common to Sections

1, 6, and

Corner consists of a None (not) in place  
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1		6
--	---	--	---

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	✓		
	✓		

Species Spruce

Diameter 8 1/2

Bearing S45°E.

Distance 16 lks.

Do you believe this to be a genuine Land Office Corner?

If not, why?

L. G. McCashin

(Signature)

Colimator

(Title)

2-23-35

(Date)

1.  
86.  
14  
1.24

57.2

Hob

Cor. Reset. 27" - 14" Spruce

Corner again.

Give any further facts which will aid in finding this

to the chains distant.

from which this Corner bears N80°E.

side of Sec. Cor.

tree 8 inches diameter, on the East

Metal Location Poster is on a Spruce

	Sec.		Sec.
	Sec.	1	Sec.
	6		

(Make sketch of topography near Corner)