

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

L-3

L-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th Mer.

Center 1/4 Corner common to Sections
18, and

Corner consists of a Tamarack (not) in place

State condition Good.

Dimensions above ground 3 x 3 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
C.		C.	
S.		S.	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4			
S.			
BT			

Species Tamarack

Diameter 6"

Bearing N. 63° W.

Distance .27 chains

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

E. Bowman

E. Bowman

(Signature)

Enrollee

(Title)

3/28/36


(Date).

Corner again.
Give any further facts which will aid in finding this

chains distant.

27
from which this Corner bears N. 71° E.

side of Tree
tree 7 inches diameter, on the west
Metal Location Poster is on a Tamarack



(Make sketch of topography near Corner)

L-3

Mr. 473

5th

R. 31 W.

T. 148 N.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

L-3
L-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th Mer.

Center 1/4 Corner common to Sections

18, and _____

Corner consists of a Tamarack ~~(now)~~ in place

State condition Good.

Dimensions above ground 3 x 3 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>		<u>1/4</u>	
<u>C.</u>		<u>C.</u>	
<u>S.</u>		<u>S.</u>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>			
<u>S.</u>			
<u>BT</u>			

Species Tamarack

Diameter 6"

Bearing N. 65° W.

Distance .27 chains

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. Bowman

E. Bowman

(Signature)

Forester

(Title)

3/28/36

(Date)

Corner again. Give any further facts which will aid in finding this


chains distant.

from which this Corner bears N. 71° E.

side of

tree 7 inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

7-3

43

55

R. 31 W.

T. 148 N.