

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

*U-4
 checked
 10-4*

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th Mer.

#1 - 1/16 Corner common to Sections
 30, and 31

Corner consists of a Oak Stake (not) in place



State condition Good

Dimensions above ground 48 x 3 x 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	1/16	1/16	35
BT	BT	BT	

Species Birch Balsam Maple

Diameter 10" stump 10" 18"

Bearing N. 86° W. S. 3° W. S. 3° W.

Distance .27 ch. .12 ch. .70 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

3 fairbanks

Ted Fairbanks

(Signature)

3/23/36

(Date)

Enrollee

(Title)

East & West blazed line

Corner again.

Give any further facts which will aid in finding this


12 chains distant.

from which this Corner bears N. 30° E.

side of Tree

10 inches diameter, on the North

Metal Location Poster is on a Balsam



(Make sketch of topography near Corner)

M.G. 1-4

T. 148 N. R. 31 W.

U. S. Department of Agriculture

Submitted *GG* FOREST SERVICE

V-4
V-4

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148* R. *31* Mer. *5*

1/16 # 1 Corner common to Sections
30, 31, and

Corner consists of a *Rotten Post* (not) in place
State condition *Decayed*

Dimensions above ground *48"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Balsam Birch*

Diameter *11"* *8"*

Bearing *S* *W*

Distance *10'* *25'*

Do you believe this to be a genuine Land Office Corner? *Yes*


If not, why? _____

Johnson
(Signature)
Const For
(Title)

12/13/35
(Date)

Corner again.

Give any further facts which will aid in finding this
 ----- chains distant.
 ----- from which this Corner bears
 ----- side of
 ----- tree ----- inches diameter, on the
 ----- Metal Location Poster is on a



(Make sketch of topography near Corner)

5-V-4
 Mel
 V-4
 T. 1/8 R. 31

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

V-4
V-4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 31 5 Mer.



1/16 #1 Corner common to Sections
30, 31, and

Corner consists of a Rotten Post (not) in place
State condition Decayed

Dimensions above ground 48" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Balsam Birch
 Diameter 11" 8"
 Bearing S W
 Distance 10' 15'

Do you believe this to be a genuine Land Office Corner? *yes*
If not, why? _____

J. I. Moon

(Signature)
(Const. For.
(Title)

12/19/34
(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. 148 R. 31 S. 1-4 V-4 Met.

1/81