

U. S. Department of Agriculture
FOREST SERVICE

C-7
C-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th Mer.

Center 1/4 Corner common to Sections
5, and

Corner consists of a Stakes (not) in place
State condition Good.

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

		1/4 CS	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4			
BT			

Species 4

Diameter 6"

Bearing S. 70° W.

Distance .05 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

B. Brooks

B. Brooks

(Signature)

Enrollee

(Title)


4/9/36

(Date)

Corner again.
Fence running South also fence
running West just inside of type line
of Swamp.

Give any further facts which will aid in finding this
chains distant.

27
from which this Corner bears
N. 52° E.
side of Tree
tree 7 inches diameter, on the NE
Metal Location Poster is on a Tree



(Make sketch of topography near Corner)