

U. S. Department of Agriculture
FOREST SERVICE

R-13
R-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th Mer.

Section _____ Corner common to Sections
21, 22, 28, and 27

Corner consists of a _____ (not) in place



State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 148
R. 31
S. 21

T. 148
R. 31
S. 27

BT

BT

Species White Ash Birch

Diameter 5" 10"

Bearing N. 43.38 E. S. 43.38 E.

Distance .60 ch. .57 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

T. Fairbanks

T. Fairbanks

(Signature)

Enrollee

2/11/38

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

8-13
MGT.

T. 148 N., R. 31 W., S. 5th

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

P 213
R-36
R-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148* R. *31* *5th* Mer.

Section Corner common to Sections
21, 22, 27, and 28



Corner consists of a *wooden stake* (not) in place
 State condition *fair*

Dimensions above ground *14* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T148
R-31
S-21

T148
R-31
S-22

T148
R-31
S-27

BT

BT

BT

Species *Asb Spruce Birch*

Diameter *5" 10" 12"*

Bearing *N49W N61E S37E*

Distance *43ch 53ch 77ch*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

Waldson
 (Signature)

12/2/34
 (Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

<p>Sec. 27</p>	<p>Sec. 28</p>	<p>Sec. 21</p>	<p>Sec. 22</p>
<p>Sec. 27</p>	<p>Sec. 28</p>	<p>Sec. 21</p>	<p>Sec. 22</p>

(Make sketch of topography near Corner)

T. 148 R. 31
 5-2
 R-13
 K-13
 Mer 13

U. S. Department of Agriculture
FOREST SERVICE

R-13
36
R-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 31 5th Mer.

Section Corner common to Sections
21, 22, 27, and 28

Corner consists of a wooden stake (not) in place
State condition fair

Dimensions above ground 14 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 148 R-31 S-21	T 148 R-31 S-22	T 148 R-31 S-27	
BT	BT	BT	

Species Ash Spruce Birch

Diameter 6" 10" 12"

Bearing N49W N61E S37E

Distance 43.0 53.0 27.0


Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Handerson
(Signature)

12/12/34
(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 118 R. 3
 Mer. R-13
 K-13

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

R-13
R-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th Mer.

Section _____ Corner common to Sections
21, 22, 23, and 27

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 148
R. 31
S. 21

--

--

T. 148
R. 31
S. 27

BT

--

--

BT

Species White Ash _____ Birch _____

Diameter 6" _____ 10" _____

Bearing N. 45.30 E. _____ S. 45.30 E. _____

Distance .60 ch. _____ .57 ch. _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

T. Fairbanks

T. Fairbanks

(Signature)


Enrollee

2/11/35

(Date)

(Title)

Metal Location Poster is on a
 tree _____ inches diameter, on the
 side of _____
 from which this Corner bears
 _____ chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

Mer. 8-13
 8-13

T. M. R. H. W.