

L-22

U. S. Department of Agriculture

L-22

Submitted GG FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 31W 5 Mer.

#9-1/16

Corner common to Sections

and 13

Corner consists of a Post (not) in place

State condition poor

Dimensions above ground 38 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species T T

Diameter _____

Bearing W NE

Distance 32 82

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

G. D. Bauch

(Signature)

12/18/35

(Date)

J. F.

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mt. 22
1-22

T. 148 N. R. 31 W. 5

L-22

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

L-22

CORNERS OF THE PUBLIC SURVEY

T. *148N* R. *31W* *5* Mer.

#9-1/16

Corner common to Sections

and *13*

Corner consists of a *Post* ~~(not)~~ in place


State condition *poor*

Dimensions above ground *28"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *T* *T*

Diameter _____

Bearing *W* *NE*

Distance *3L* *8L*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

G. D. Bauck

(Signature)

12/18/35
(Date)

J.F.
(Title)

L-22
Already
Posted
L-22

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th Mer.

1/16 Corner common to Sections
13, and

Corner consists of a Post (set) in place


State condition Poor

Dimensions above ground 28 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tam. Tam.

Diameter

Bearing W/ NE

Distance 3 links 8 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

G. D. Bauch

G. D. Bauch

(Signature)

(Title)

12/18/35

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

4-22
Mer.
1-22

5th

T. 148 N. R. 31 W.