

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 31 W 5th P. Mer.
North Quarter Corner common to Sections

1 and only

Corner consists of a Oak post (not) in place



State condition Poor

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.T.'s			
1/4 S 1.			IN
B.T.			

Species Maple Basswood stump

Diameter 10" 14"

Bearing S. 15° E N. 24° E

Distance 34 24

Do you believe this to be a genuine Land Office Corner? Yes


If not, why?

C.T. Vanspankeren
(Signature)

1/12/39
(Date)

Compass Man
(Title)

Metal Location Poster is on a Elm
 tree 8 inches diameter, on the N.E.
 side of Tree
 from which this Corner bears N.58°E
 0.24 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. 1. 148 N. R. 31 W. 5th P. A-23 Mer. H-23

U. S. Department of Agriculture
FOREST SERVICE

A-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

148 N. R. 31 W. 5th Mer.

N. 1/4 cor. Corner common to Sections

1, and 36

Corner consists of a Cedar post (not) in place

State condition Poor

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4 S.			
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

148-31			
	148-31		
BT	BT		

Species Maple Cedar

Diameter 14 10

Bearing SE N

Distance 25 lks. 25 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

G. D. Bauch

G. D. Bauch

(Signature)

C. F.

(Title)

12/13/35

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 146 N. R. 31 W. 5th Mer.

A-23

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

A-23
 A-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 100 N R. 51 W 8th P. Mer.

North Quarter Corner common to Sections

1 only

Corner consists of a Oak post (not) in place


State condition Fair

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Maple Redwood stump

Diameter 10" 14"

Bearing S. 15° W N. 94° E

Distance 34 24

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

G. T. Thompson
 (Signature)

1/12/39
 (Date)

Compass Man
 (Title)

Blank ruled lines for text entry.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

A-23

A-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 31 W. 5th P. Mer.

North Quarter Corner common to Sections
....., 1, and 17

Corner consists of an oak Post (~~not~~) in place

State condition Poor

Dimensions above ground 30 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>0719. B.Ts.</u> <u>1/4 S</u> <u>1</u>			
<u>B.T.</u>			

Species Maple Basswood Sp.

Diameter 10" 14"

Bearing S. 15° E. N. 24° E.

Distance 34 24

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

C. Vanspankern

(Signature)


Compass Man

(Title)

1/12/39

(Date)

Metal Location Poster is on an Elm tree 8 inches diameter, on the NE side of Tree from which this Corner bears 0.24 chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 198 N. R. 31 W. 573 P. Mer. A-23 A 35

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

A-23
 A-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 31 5 Mer.

N 1/4 Cor. Corner common to Sections
1, _____, and 36



Corner consists of a Cedar post ~~not~~ in place
 State condition poor

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

148-31 BT	148-31 BT		

Species	<u>Maple</u>	<u>Cedar</u>	_____
Diameter	<u>14</u>	<u>10</u>	_____
Bearing	<u>SE</u>	<u>N</u>	_____
Distance	<u>256.</u>	<u>256.</u>	_____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

13/12/35
 (Date)

(Signature)
G. D. Bauch, S. E.
 (Title)

