

U. S. Department of Agriculture
FOREST SERVICE

J-25
J-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148 N* R. *3/W* *5th* Mer.

Sec. *12, 13, 7, and 18* Corner common to Sections

Corner consists of a *Post* (not) in place
State condition *Post good*

Dimensions above ground *24"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>12</i>		<i>13</i>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *County Survey*


G. D. Bauch
(Signature)

S. F.
(Title)

12/19/35
(Date)

Corner again.
 The corner is on the west
 side of the road, approx. 1/4 N
 of a knoll and in the edge of a bog.

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 148N R. 31W 5th. S-25 Mer.