

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

L-24,25  
L-24,25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 31W 5th Mer.



Mc on 1/4 Line Corner common to Sections  
W of E 1/4 Cor., and 13

Corner consists of a Post (not) in place  
State condition good

Dimensions above ground 24 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar  
Diameter 8"  
Bearing NW  
Distance 10 ft

Do you believe this to be a genuine Land Office Corner? yes  
If not, why? \_\_\_\_\_


G. D. Bauch  
(Signature)

S. F.  
(Title)

12/19/35  
(Date)

Corner again.  
The corner is directly W. of  
the fence corner, as shown  
above.

Metal Location Poster is on a  
tree inches diameter, on the  
side of  
from which this Corner bears  
chains distant.  
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 149 N. R. 31 W.  
S. 11 L. 24. 25  
M.D. 24. 25