

U. S. Department of Agriculture
FOREST SERVICE

A9

poster

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *49* R. *25* Mer. *5*

Sec 4 Corner common to Sections *4*, *5*, *32*, and *33*

Corner consists of a *Stake* (not) in place

State condition *Poor*

Dimensions above ground *12* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

John Kirkwood
(Signature)

Nov 10, 1933
(Date)

Estimator
(Title)

1/2 chain East of river

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 119 R. 25 Mer. 5 A-9