

U. S. Department of Agriculture
FOREST SERVICE

Superior
~~25~~
Posted
2-5

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 25 W 5th Mer.

SECTION Corner common to Sections
31, 32, and

Corner consists of a WOODEN STAKE (not) in place
State condition BADLY DECAYED + FIRE SCARRED

Dimensions above ground 3 X 3 X 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<u>5</u>			<u>5</u>
<u>31</u>			<u>32</u>
			<u>T149N</u>
			<u>R25W</u>
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner?

If not, why? _____

Ralph F. Johnson

(Signature)

Sept. 21, 1934

(Date)

Carl Johnson

(Title)

TYPE BRUSH

ROAD TURNS AT CORNER
AS SHOWN

Corner again.

Give any further facts which will aid in finding this


chains distant.

0.63
from which this Corner bears S. 14 3/4° E.

side of TREE

tree inches diameter, on the S. SIDE

Metal Location Poster is on a BIRCH



(Make sketch of topography near Corner)