

U. S. Department of Agriculture
FOREST SERVICE

53

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 26W 5th Mer.

Quarter Corner common to Sections
7, and 18

Corner consists of a --- (not) in place

State condition -----

Dimensions above ground ----- inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

B.T			

Species Tamarack Snag

Diameter 12

Bearing N30°E

Distance 67 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

A. Adams


(Signature)

9/10/34
(Date)

Asst. Forester CCO

Corner again.

Give any further facts which will aid in finding this
chain distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)