

U. S. Department of Agriculture

FOREST SERVICE

J-5

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 24 - 2 Mer.

Corner common to Sections

7, 8, 17, and 18

Corner consists of a Spruce Stake in place

State condition fair

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 6			
BT			

Species S

Diameter 8"

Bearing S 38 E

Distance 33"

Do you believe this to be a genuine Land Office Corner? No

If not, why? Bearing tree found
Carpenter with original
notches but the height of
tree looks like 10 ft high

(Signature)

Jr. Forest Guard

(Title)

9-13-40
(Date)

J-5

Corner again.

Give any further facts which will aid in finding this

~~chains distant.~~

331

from which this Corner bears

N 37° W


side of

Spoad

tree 8 inches diameter, on the

Spreads

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. R. Mer.