

U. S. Department of Agriculture
FOREST SERVICE

P
V
7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 26 W 5th Mer.

Quarter Corner common to Sections
-----, -----, 29, and 32

Corner consists of a Aspen Post ~~(rod)~~ in place
State condition Good (New Post Set)

Dimensions above ground 36 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

MKd. N. in BT.

1/4 S 29

Marks rotted out

1/4 S 29

--

BT

--

BT

--

Species Tam Dead Aspen Spruce

Diameter 4" 10" 4"

Bearing N14°E S4°E N62°30'W

Lks. Distance 136 253 65

Do you believe this to be a genuine Land Office Corner? yes

If not, why? -----

J. A. Gjelhaug
(Signature)

12/31/35
(Date)

Jr. Civil Eng
(Title)

Corner again.

Give any further facts which will aid in finding this


0.65 chains distant.

from which this Corner bears S 62° 30' E

side of tree

tree 4 inches diameter, on the S.E.

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. 5th Mer.