

U. S. Department of Agriculture
FOREST SERVICE

79
Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 26W 5th Mer.
Quarter
Corner common to Sections
29, and 28

Corner consists of a ----- (not) in place
State condition -----

Dimensions above ground ----- inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 29

1/4 S 28

--

--

B.T.

B.T.

--

--

Species Elm Aspen
Diameter 10" 14" (Taken from approx.
Bearing N 50° E N 56° W corner).
Distance 0.68ch. 0.180chains.

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? -----

H. Bland
(Signature)

Chief of Party.

3/29/35
(Date)

(Title)

