

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

SUPP.
P
34

89

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 26 W 5th Mer.

Quarter Corner common to Sections
20, and 21

Corner consists of a Cedar Post (~~stone~~) in place
State condition Good

Dimensions above ground 36 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>0m 85</u> <u>1/4 S</u>			

Species Cedar

Diameter 7"

Bearing East

415 Distance 5

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

L. A. Gjelhaug
(Signature)

Jr. Civil Eng
(Title)

2/14/36
(Date)

Corner again.

Give any further facts which will aid in finding this


0.05 chains distant.

from which this Corner bears West

side of stump (5' high)

tree 7 inches diameter, on the West

Metal Location Poster is on a Cedar Stp (B.T.)



(Make sketch of topography near Corner)

T. 149N R. 26W S. 74 Mer.