

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *149 N* R. *26 W* *5th* Mer.Section Corner common to Sections
*16, 17, 20, and 21*Corner consists of a *Birch Post* in place
State condition *Good*Dimensions above ground *24* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>T. 149 N</i> <i>R. 26 W.</i> <i>S. 17</i>			
<i>B. T.</i>			

Species *N. Pine Str.*Diameter *8"*Bearing *N. 21° W**LN* Distance *23*Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

J. A. Gjelhaug

(Signature)

Jr. Civil Eng.

(Title)

2/11/36

(Date)

Corner again.

Give any further facts which will aid in finding this


0.22 chains distant.

from which this Corner bears S. 15° W.

side of tree

tree 3 inches diameter, on the South

Metal Location Poster is on a N. Pine



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. S. 27 Mer.