

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE



C9
P

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 149N R. 26W 5th Mer.
Quarter Corner common to Sections

-----, -----, 4, and 5
Corner consists of a Ash Post (~~net~~) in place
State condition Good

Dimensions above ground 36 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of ----- is located -----
----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4 5'</u> <u>Orig BT</u> <u>BT</u>			

Species Balsam Spruce
Diameter 7" 6"
Bearing S64°W S53°W
LKs Distance 26 16 1/2

Do you believe this to be a genuine Land Office Corner? yes
If not, why? -----

J A Gjelhaug
(Signature)

9/19/35
(Date)

Jr Civil Engr
(Title)

Found one Orig BT clown & rotten
Set New Ash post & placed poster on
Spruce

Corner again.

Give any further facts which will aid in finding this


16 1/2 chains distant.

from which this Corner bears N 53. E

side of Tree

tree 6 inches diameter, on the NE

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

T. 149N R. 26W G-14 Mer.