

U. S. Department of Agriculture

FOREST SERVICE

N13  
P  
36

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 26 W 5th Mer.

Section Corner common to Sections  
15, 16, 21, and 22

Corner consists of a Wood Post (~~not~~) in place

State condition Fair (Scribed)

Dimensions above ground 14 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Opp. BT  
T. 149 N  
R. 26 W  
S. 22

New BT  
S. 16

--

--

B.T.

B.T.

--

--

Species Tam. Spruce

Diameter 6" 6"

Bearing S. 42° E N. 24° W

Distance 15 32

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

J. A. Gjelhaug  
(Signature)

2/3/36  
(Date)

Jr. Civil Eng.  
(Title)

N-13

Corner again.  
Give any further facts which will aid in finding this


0.15 chains distant.

from which this Corner bears *N. 42° W*

side of *Tree*

tree *6* inches diameter, on the *N.W.*

*Tam* Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. 57A Mer.