

U. S. Department of Agriculture

FOREST SERVICE

G13
P

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 149N R. 26W 5th Mer.

Quarter Corner common to Sections
9, and 10

Corner consists of a Cedar Post (~~not~~) in place



State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/45 10			
Orig. BT			
BT			

Species Cedar Balsam

Diameter 7 5

Bearing S. 50° E N 45°

Distance 9 5 1/4

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

J A Gjelhaug

(Signature)

9/18/35
(Date)

Jr Civil Engr
(Title)

Corner is located in Cedar Swamp
2 chs. E. of Rd.

Corner again.

Give any further facts which will aid in finding this


chain distant.

From which this Corner bears $S 45^{\circ} W$

side of Tree

tree 6 inches diameter, on the $S W$

Metal Location Poster is on a Balsam



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. 5th Mer.