

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

A13
X

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 149N R. 26W 5TH Mer.

Section Corner common to Sections
3 & 4, 33, and 34 T150N R26W

Corner consists of a 1" Oak Post (~~rod~~) in place

State condition Good

Dimensions above ground 60 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Placed Post			

Species N. Pine

Diameter 12"

Bearing N. 33° E

Distance 25

Do you believe this to be a genuine Land Office Corner? yes

If not, why? Found old post down. Set new Oak Post 4" x 6" old BTs all gone.

J. A. Gjelhaug
(Signature)

Jr. Civil Engr.
(Title)

10/3/35
(Date)

Corner again.

Give any further facts which will aid in finding this


0.25 chains distant.

from which this Corner bears S 33° W

side of ~~Tree~~

tree 12 inches diameter, on the South

Metal Location Poster is on a N. Pine



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. S. 14 Mer.