

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

P
27
36

R17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 26W 5th Mer.
Section Corner common to Sections
22, 23, 26, and 27

Corner consists of an Iron Pipe 1 1/2" in place
State condition Good

Dimensions above ground 12" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

J. A. Gjelhaug
(Signature)


Jr. Civil Eng.
(Title)

2/4/36
(Date)

Corner again.
 Iron pipe $1\frac{1}{2}$ " above ground
 at Fence Corner. Settler living at
 Bass Lake Store Post Office, says
 this is correct corner.

Give any further facts which will aid in finding this
 chains distant.

from which this Corner bears $N 95^{\circ} W$
 side of Willow
 tree 3 inches diameter, on the NW
 Metal Location Poster is on a Willow



(Make sketch of topography near Corner)

T. 149 N R. 26 W 5th Mer.