

N21

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 26 W 5th Mer.

Section Corner common to Sections 13, 14, 23, and 24

Corner consists of a Iron Pipe (not) in place

State condition Good

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	Orig B.T.	Orig B.T.	Placed Poster
BT	BT	BT	

Species W. Pine Str Maple Linden Maple

Diameter 36" 12" 10" 7"

Bearing S. 12° E N 84 1/2° E S 81 1/2° E N 78° W

Links Distance 8 37 44 21

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

J A Gjelhaug

(Signature)

9/26/35

(Date)

Jr. Civil Engr.

(Title)

Corner again.

Give any further facts which will aid in finding this

0.21 chains distant.


from which this Corner bears

5.78° E

side of Tree

tree 7 inches diameter, on the East

Metal Location Poster is on a Maple



(Make sketch of topography near Corner)

T. 149N. R. 26W. 514 Mer.