

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 26W 5th Mer.

Section Corner common to Sections

11, 12, 13, and 14Corner consists of a Aspen Post (~~post~~) in placeState condition GoodDimensions above ground 40" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig	T149N		
BT	R.26W	Poster	
	513		
	B.T.		

Species Tam. BalsamDiameter 10" 3"Bearing S.50E S.88°WEDistance 3.5 46Do you believe this to be a genuine Land Office Corner? yes

If not, why?

J.A. Gjelhaug


(Signature)

9/23/35

(Date)

Jr Civil Engr

(Title)



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. 5-74 Mer.

A little North of Rol. intersection
West and North

Corner again.
Give any further facts which will aid in finding this

O.M.C. chains distant.

from which this Corner bears
side of *Tree*

tree 3 inches diameter, on the *West*

Metal Location Poster is on a *Balson*