

U. S. Department of Agriculture  
FOREST SERVICE

P 57  
36  
G 21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 26W 5<sup>th</sup> Mer.

Quarter Corner common to Sections

11, and 12

Corner consists of a Aspin Post (~~net~~) in place



State condition Good

Dimensions above ground 4.8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spruce Stp ASPIN

Diameter 8" 5"

Bearing S 68° E N 85 1/2° W

LKS Distance 4.4 4.8

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

J. A. Gjelhaug  
(Signature)

9/20/35  
(Date)

Jr Civil Engr  
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 149 R. 26W 51k Mer.