

V25

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 26W 5<sup>th</sup> Mer.

Section Corner common to Sections  
25, 26, 30, and 31 R25W

Corner consists of at top Center of Rd (not) in place

State condition Good flush with Rd

Dimensions above ground 0 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County BT	Placed Poster		
BT			

Species Tam Spr Aspen

Diameter 7" 5"

Bearing N54°15'E N4°W

Lks Distance 15.8 5.4

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Old Orig Line Tree on  
Line 1 ch No

J. A. Gjølhaug

(Signature)

10/2/35

(Date)

Jr Civil ENGR

(Title)

Corner again.

Give any further facts which will aid in finding this


0.54 chains distant.

from which this Corner bears S. 40° E.

side of Tree

tree 5 inches diameter, on the South

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 149 N. R. 26 W. 574 Mer.