

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

G25  
P

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 26 W 5<sup>th</sup> Mer.

Quarter Corner common to Sections  
12, and 7

Corner consists of a *Aspin Post* (not) in place

State condition *Good*

Dimensions above ground *36* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *N. Prae Stp Aspin*

Diameter *20"* *4"*

Bearing *S 87° E* *N 41° W*

*LKS* Distance *12* *18*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*J A Gjelhaug*

(Signature)

*Jr Civil Engr*

(Title)

*9/20/35*

(Date)

Small rocks piled around  
Car. Post

Corner again.

Give any further facts which will aid in finding this


0.18 chains distant.

from which this Corner bears S 41° E

side of

tree 4 inches diameter, on the S.E.

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 149N R. 26W S. 74 Mer.