

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 28 5 Mer.

1/4 Corner common to Sections 8, and 9

Corner consists of a \_\_\_\_\_ (not) in place

State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S-8	S-8		
-----	-----	--	--

B.T.	B.T.		
------	------	--	--

Species Bal. P. Stp.

Diameter 10" 15"

Bearing S10°W N38°W

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Lloyd H. Johnson

(Signature)

Surveyor

(Title)

1-17-34

(Date)

Road E and W  
Corner in Road.

Corner again.

Give any further facts which will aid in finding this


.53 chains distant. From Center Road.

from which this Corner bears S 20° E

side of Road

tree 6 inches diameter, on the South

Metal Location Poster is on an ASPEN



(Make sketch of topography near Corner)

Mer. G-9

T. 149 R. 28 S.

69

U. S. Department of Agriculture

FOREST SERVICE

posted

*Chipmunk*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 28 Mer. 5

Corner common to Sections 14, 8, and 9

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>58</u>	<u>55</u>		<u>5</u>
<u>57</u>	<u>57</u>		

Species B.P. B.S.P.

Diameter 10 15

Bearing S42°W N38°W

Distance \_\_\_\_\_


Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Fred W. Johnson  
 (Signature)  
Jan. 17 1931  
 (Date) Surveyor  
 (Title)

Metal Location Poster is on a *22.5 ft x 21* tree *6* inches diameter, on the *Smith* side of *Road* from which this Corner bears *53* chains distant. *from Smith* Give any further facts which will aid in finding this Corner again.

*Road*  
*Corner in Road*



(Make sketch of topography near Corner)