

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 28 W 5th Mer.

Sec. 16, 15, 21, and 22
Corner common to Sections

Corner consists of a Post (not) in place

State condition Partly Decayed

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

T-149		R-28	
521		516	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T-149 N R-28 521			
BT			

Species SPR

Diameter 5 1/2

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Hanks
(Signature)

T. F. F36
(Title)

4/13/34
(Date)

N-13

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

found



(Make sketch of topography near Corner)

T. 49 N. R. 28 E. Mer. 546