

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

E-19

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 28 W 5 P Mer.

1/4 Corner common to Sections  
2, \_\_\_\_\_, and 11

Corner consists of a Spruce Stake (rust) in place  
 State condition Good

Dimensions above ground 18 x 3 x 3 inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		1/4	
2		S	11
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4	1/4		
B.T.	B.T.		

Species Juniper Juniper

Diameter 10 10

Bearing S 20° 30' W - N 30° W

Distance 51.5 32

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Hamre by N.C. Norman  
 (Signature)

Oct. 11, 1935  
 (Date)

LEIM.  
 (Title)

E-19

Corner again.

Give any further facts which will aid in finding this


13.5 links - chains distant.

from which this Corner bears S 27° W

side of tree

tree 9 inches diameter, on the SW

Metal Location Poster is on a Black Corner



(Make sketch of topography near Corner)

T. 149 N R. 28 W S P Mer.

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

EM  
 ✓

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 28 W 5th Mer.

1/4 Corner common to Sections  
2, \_\_\_\_\_, \_\_\_\_\_, and 11

Corner consists of a SPRUCE STAKE (not) in place  
 State condition GOOD

Dimensions above ground 18" x 3" x 3" inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 2		1/4 S 11	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S	1/4 S		
BT	BT		

Species TAM TAM

Diameter 10" 10"

Bearing S82°50'W N36°W

Distance 615 LINKS 32 LINKS

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

\_\_\_\_\_

Oct 11 1935 H. C. Norman  
 (Date) (Signature)  
L. E. M. T. F.  
 (Title)

Corner again.

Give any further facts which will aid in finding this


*13.5 LINKS distant.*

from which this Corner bears *S 27° W*

side of *AREA*

tree *9* inches diameter, on the *S.W.*

Metal Location Poster is on a *BALD SPRUCE*



(Make sketch of topography near Corner)

T. 142N R. 28W S. 71 Mer.

U. S. Department of Agriculture

FOREST SERVICE

E-19

Chippewa NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 28 W 5<sup>th</sup> Mer.

$\frac{1}{4}$  Corner common to Sections  
 \_\_\_\_\_, \_\_\_\_\_, 2, and 11

Corner consists of a Spruce Stake (not) in place  
 State condition Good

Dimensions above ground 18" x 3" x 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

5		$\frac{1}{4}$	
2		S	
		11	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$	S
---------------	---

$\frac{1}{4}$	S
---------------	---

--	--

--	--

BT
----

BT
----

--

--

Species Tam Tam

Diameter 10" 10"

Bearing S83°W N36°W

Distance 61 1/2 32 1/2

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Field Man. Hemre (L.E.M.)

H. Norman  
 (Signature)

Oct. 11, 1935  
 (Date)

J. F.  
 (Title)

E-19

Corner again.  
Give any further facts which will aid in finding this


0.13 chains distant.

From which this Corner bears S 27° W

side of Tree

1 inches diameter, on the SW

Metal Location Poster is on a Black Spruce



(Make sketch of topography near Corner)

T. 149 N R. 28 W Men

U. S. Department of Agriculture

FOREST SERVICE

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149N R. 28W 5TH Mer.

1/4 Corner common to Sections 2, \_\_\_\_\_, \_\_\_\_\_, and 11

Corner consists of a SPRUCE STAKE (~~not~~) in place  
State condition GOOD

Dimensions above ground 18" x 3" x 3" inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		1/4	
2		3	
		11	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S	1/4 S		
BT	BT		

Species TAM TAM

Diameter 10" 10"

Bearing S 81° 0' W N 36° W

Distance 61.5 LINKS 38 LINKS

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

H. C. Norman  
(Signature)

OCT 11, 1935  
(Date)

L. E. M.

TF  
(Title)

Corner again.

Give any further facts which will aid in finding this


13.5 LINKS ~~obscure~~ distant.

from which this Corner bears S 27° W

side of TREE

tree 9 inches diameter, on the SW

Metal Location Poster is on a BLACK SPRUCE



(Make sketch of topography near Corner)

T. 144 N. R. 28 W. 574 Mer.