

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

P1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 29 W 5th. P. Mer.
Quarter

Corner common to Sections

19, and 24 T.149NR.30W

Corner consists of a Wood Post (set) in place

State condition Good

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. BT

--	--	--	--

BT

--	--	--	--

Species Spruce Down

Diameter 14"

Bearing N60°E

Distance 9

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? _____

John A. Gjelhaug

(Signature)


5/17/39

(Date)

Jr. Civil Eng.

(Title)

Corner again.
 Give any further facts which will aid in finding this
 chains distant.
 0.10
 from which this Corner bears
 S21°E
 side of
 Stump
 inches diameter, on the
 tree
 10
 Metal Location Poster is on a
 Elm Stump
 South



(Make sketch of topography near Corner)