

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

N3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 29 W 5th. P. Mer.

Quarter Corner common to Sections

18, and 19

Corner consists of a Cedar post (not) in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

New BT

Orig. BT		$\frac{1}{4}$ S 19	
BT		BT	

Species W.P.Stp. Aspen

Diameter 16" 2"

Bearing N38°E S22°W

Distance 12 18½

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? _____

John A. Gjelhaug

(Signature)


6/12/39

(Date)

Jr. Civil Eng.

(Title)

Metal Location Poster is on a Aspen
 tree 2 inches diameter, on the N.E.
 side of Tree
 from which this Corner bears N22°E
0.198 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. 149 N. R. 29 W. 5th. P. Mer.