

Form 874-0—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

x5

---Chippewa--- NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 29W. 5th Mer.

----- G. L. O. ----- Corner common to Sections
 -----, -----, 31, and 32 -----

Corner consists of a Tamarack (~~rock~~) in place

State condition fair

Dimensions above ground 0 [#]Feet inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S 32		S 31
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

149 29 S31			
BT			

Species Tamarack

Diameter 10 1/2

Bearing N44 W.

Distance 40 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

Albin Trust
 Albin Trust

(Signature)

Enrollee

(Title)

12/24/36
 (Date)

Old blazed line going east and west 50 IKB, North.

Corner again.

Give any further facts which will aid in finding this


40 chains distant.

from which this Corner bears N 44° E

side of Tree

tree 10 inches diameter, on the South west

Metal Location Poster is on a Tamarack



(Make sketch of topography near Corner)