

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

X15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 29 5th Mer.

34^{1/4} Corner common to Sections
-----, -----, -----, and -----

Corner consists of a ----- (not) in place
State condition -----

Dimensions above ground ----- inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

Duffon Johnson

(Signature)

Dec. 30 - 1957

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

~~claims~~ distant.


from which this Corner bears *500 ft. West.*

side of

tree

tree *12* inches diameter, on the *South*

Metal Location Poster is on an *elm*



(Make sketch of topography near Corner)

T. 149 R. 29 5th Mer.