

U. S. Department of Agriculture  
FOREST SERVICE

V15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 29 W 5th P. Mer.

Quarter Corner common to Sections  
27, and 34

Corner consists of a Tam'c. Post (K) in place

State condition Good

Dimensions above ground 40" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Mkd. New B.T.

Orig. B.T.	B.T.	S 34	
B.T.		B. T.	

Species Aspen Stp. Elm

Diameter 18" 8"

Bearing S89°E S15°E

Distance 27 33

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

John A. Gjelhaug

(Signature)

Jr. Civil Engineer

(Title)

1/30/40

(Date)

Corner again. Give any further facts which will aid in finding this


0.23 chains distant.

from which this Corner bears S46°E

side of ~~MAPLE~~ Tree

tree 4 inches diameter, on the S.E.

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)