

U. S. Department of Agriculture
FOREST SERVICE

✓ 3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 30 W. 5th Mer.

1/4 Corner common to Sections
30, and 31

Corner consists of a Pipe in road (not) in place
State condition

Dimensions above ground 1 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spruce

Diameter 14"

Bearing N. 20° W.

Distance 112 lks. 73.9'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

E. Gorman

E. Gorman


(Signature)

Enrollee

(Title)

4/15/36

(Date)



(Make sketch of topography near Corner)

T. 148 N. R. 30 W. 5th Mer.

Metal Location Poster is on a Telephone pole
 SE
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.