

U. S. Department of Agriculture
FOREST SERVICE

R⁹
posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 R. 30 Mer. 5th

Sec Corner common to Sections
20, 21, 28, and 29

Corner consists of a center of well (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>S</u> <u>29</u>			
<u>BT</u>			

Species cedar
Diameter 14
Bearing SW
Distance 40 ft

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

1/20/33
(Date)

[Signature]
(Signature)
[Title]
(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

	Sec.		
	Sec.		

(Make sketch of topography near Corner)