

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

✓ 23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14³ N. R. 30 W. 5th P. Mer.



Quarter Corner common to Sections
 , 25 , and 36 .

Corner consists of an Aspen Post (not) in place
 State condition Good

Dimensions above ground 40 inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.T.	Mkd. New B. Ts.
	S 25
	S 25
	B.T.
	B.T.

Species	J. Pine	Stp.	J. Pine	J. Pine
Diameter	12"		3"	3"
Bearing	S 5° W.		N. 53° E.	N. 16° W.
Distance	14		21 $\frac{1}{4}$	32 $\frac{1}{2}$

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


John A. Gjelhaug
 (Signature)

Jr. Civil Eng.
 (Title)

12/6/39
 (Date)

Blank lined area for notes at the top of the page.

Corner again.
Give any further facts which will aid in finding this
chains distant.
0.21 1/2
from which this Corner bears S. 53. W.
side of Tree
tree 3 inches diameter, on the S.W.
Metal Location Poster is on a J. Pine



(Make sketch of topography near Corner)

T. 149 N. R. 30 W. 5th P. Mer.