

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

R23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T149 N R. 30 W 5th. P. Mer.
Quarter Corner common to Sections

_____, _____, 24, and 25.
Corner consists of a Cedar Post (~~rod~~) in place
State condition Good

Dimensions above ground 40 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. BTS

--	--	--	--

BT	BT		
----	----	--	--

Species Tam. Stp. Tam. Stp.

Diameter 8" 6"

Bearing S29°W N3°W

Distance 12 7

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

John A. Gjelhaug

(Signature)

Jr. Civil Eng.

(Title)

5/31/39

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.507

South

from which this Corner bears

side of


Tree

tree 5 inches diameter, on the

South

Balsam

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 149 N. R. 30 W. 5th. P. Mer.