

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

N 23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N R. 30 W 5th. P. Mer. Quarter Corner common to Sections

-----, 13, and 24

Corner consists of a Cedar Post (42) in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. BT

S 24

BT

Species Dead Birch

Diameter 8"

Bearing S 9° E

Distance 16 1/2

Do you believe this to be a genuine Land Office Corner? yes

If not, why? -----

John A. Gjelhaug

5/25/39

(Date)

(Signature)  
Jr. Civil Eng.

(Title)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


0.06 chains distant.

from which this Corner bears East

side of Tree

tree 6 inches diameter, on the East

Metal Location Poster is on a Dead Cedar



(Make sketch of topography near Corner)

T. 149 N. R. 30 W. 5th. P. Mer.