

Form 874-9—Revised May, 1918  
**U. S. Department of Agriculture**  
**FOREST SERVICE**

X-15

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 149 N. R. 31 W. 5th Mer.

Center 1/4 Corner common to Sections  
34, and \_\_\_\_\_

Corner consists of a Spruce (not) in place  
 State condition Good.

Dimensions above ground 2 x 2 x 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Center

34		1/4	
		S.	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4			
S.			
C.			
BT	BT		

Species Tam. Stump \_\_\_\_\_

Diameter 6" 10"

Bearing S. 40° W. N. 39° W.

Distance 12 ch. 17 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

E Bowman

E. Bowman  
 (Signature)

Enrollee  
 (Title)

4/13/36  
 (Date)

X-15

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this

chains distant.


12

from which this Corner bears N. 40° W.

side of Tree

tree 6 inches diameter, on the East

Metal Location Poster is on a benchmark



(Make sketch of topography near Corner)

T. 149 N. R. 31 W. 5th Mer. X-15