

U. S. Department of Agriculture
FOREST SERVICE

223

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 31 W. 5th Mer.

1/4

Corner common to Sections

24, and

Corner consists of a (not) in place



State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Maple

Diameter 8"

Bearing N. 44° E.

Distance .42

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

J. Swartz

J. Swartz

(Signature)

Enrollee


(Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of Telephone Pole from which this Corner bears 45° chains distant.

Give any further facts which will aid in finding this Corner again.

fence running North from 1/4 corner on line.



(Make sketch of topography near Corner)

T. 149 N. R. 31 W. 5th Mer. R-23