

U. S. Department of Agriculture
FOREST SERVICE

Q23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 31 W. 5th Mer.



#12 - 1/16 Corner common to Sections
24, and

Corner consists of a Scrubbed stake (not) in place
State condition Poor

Dimensions above ground 14 x 3 x 3 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____ White Pine St

Diameter _____ 14"

Bearing _____ NE

Distance _____ 1 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. Swartz

J. Swartz

(Signature)

Enrollee

(Title)

4/24/36

(Date)

Q-23


Corner again.
Fence runs North & South on line.

Give any further facts which will aid in finding this
chain distant.

30
from which this Corner bears
side of Tree

tree 9 inches diameter, on the

Metal Location Poster is on a
Ironwood



(Make sketch of topography near Corner)

T. 149 N. R. 31 W. 5th Dist. 2-23